



# Preliminary Information

## PIC6358 Unable to Tune in "Even-Numbered" Radio Station Frequencies

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro	2019	All	All	All	All

### Condition / Concern

Involved Region or Country	Chile and Columbia
Additional RPO	Equipped with radio RPO's IOS or IOT only.
Condition	Some customers may notice that they are unable to tune into an "Even-Numbered" radio station frequency, for example, 98.2 FM.
Concern	This concern is caused by vehicles that were built with an incorrect radio calibration file.

### Correction:

GM is aware of this software anomaly. A fix is currently under development. In the meantime, do NOT replace the radio, or make any other repair attempts for this concern. Once a final repair has been released, this PIC will be converted into a bulletin with further instructions.

### Version History

Version	1
Modified	03/29/2019 - Created on



GENERAL MOTORS