



# Preliminary Information

## PIP5332A Transmission oil in the TPIM at the AUX pump connector

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2011 - 2015	All	All	All	All
Cadillac	ELR	2014 - 2015	All	All	All	All

### Supersession Statement

This PI was superseded to update Recommendation/Instructions. Please discard PIP5332.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

**Transmission fluid found in the Power Inverter Module (PIM) aux pump connector.**

### Recommendations / Instructions

**Please replace the Aux pump with new harness and clean T6 Power Inverter Module (PIM) connections.**

**Note: During Drive unit repairs you may notice transmission fluid in the T6 Power Inverter Module (PIM). Do not replace the T6 PIM.**

**Tilt the T6 PIM so we came remove as much fluid from the PIM as possible and reinstall on vehicle.**

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS