



Preliminary Information

PIC6363 Diagnostic Information On Low Beam Headlight Bulb Replacement.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2019	All	All	L3A	MKV

Involved Region or Country	North America
Condition	Some dealers may experience a concern where the low beam headlamp bulb is inoperative.
Cause	After further diagnosis in SI, the tech may find that the issue is with the low beam LED bulb and the technician may be looking for the replacement procedure in SI for replacing the low beam bulb.

Correction:

If the diagnosis leads to an issue with the low beam headlight bulb, the complete headlight assembly will need to be replaced for the affected side. The low beam LED bulb is not available separately and is part of the headlamp assembly.

Note: The high beam headlamp bulb is replaceable bulb. The headlamp replacement procedure in SI is only for the high beam headlamp bulb.

Warranty Information

For vehicles repaired under the EV coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2040510	Headlamp Replacement	Use Published Labor Operation Time
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	05/13/2019 - Created on



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.