



# Service Manager Bulletin

TITLE:

**Updates to Customer Software**

<b>GROUP:</b> 30	<b>NO:</b> 001	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>REFERENCE BULLETINS:</b> TJ 31543, TJ 34820			<b>ISSUE DATE:</b> 2019-05-20	<b>STATUS DATE:</b> 2019-05-20
<b>Service Personnel:</b> Read and initial	<b>SERVICE MANAGER</b>	<b>SERVICE WRITER</b>	<b>WARRANTY ADMINISTRATOR</b>	<b>Page 1 of 3</b>

**“Right first time in Time”**

Volvo Cars is constantly developing the in-car systems and the services offered to customers, so that their cars give them the best experience possible.

As of May 13th, 2019, when the software in your customer’s vehicle is updated via *Service 2.0* or *Total Upgrade (TJ 31543)*, the customer will have access to the functions and improvements in the attached document.

It is recommended that this document be printed out and a copy provided to the customer when their vehicle is returned to them after a service.

<b>Volvo Car Customer Service</b>	
<b>TJ Instruction</b>	
<b>TJ No 34820</b>	
Date May 13-2019 Issue 01	
<b>Title</b>	Updates to the customer's software, May 2019

- Improved logic for rear seat belt reminders. The audible signal will stop when the vehicle stops and restart when the vehicle is moving.
- Changed optimization for engine noise compensation. There is a slight change in sound.
- Improved feedback for **Pilot Assist**. Under certain conditions, the steering wheel vibrates slightly when **Pilot Assist** steering assistance is disconnected, adaptive cruise control remains active. The same vibration is used that Lane Keeping Aid uses when the vehicle is starting to veer over the lane markings.
- Amended messages in the driver display (12-inch) for the Start/Stop function. A start/stop symbol has been added and the texts "Ready" and "Off" have been removed. **Note that this is not applicable to Twin Engine models.** The start/stop function switches off the engine temporarily at a standstill and then starts it automatically when it is needed. Previously, a message was shown in the tachometer when the function was available. This has been replaced with the following symbols when the function is available:



*White – Displayed in the tachometer when the function is available but the engine is running (vehicle is in motion).*



*Green – Shown in the tachometer when the function is active and the engine is auto-stopped.*



*Gray – When the symbol is grayed out with a line through it, the function is not available.*

If no symbol is shown, the function is switched off in the vehicle functions menu.

Example:



*The function is active and the engine is auto-stopped.*

- Updates to **Apple CarPlay**:
  - Simplified start-up after an **iPhone** has been connected.
  - Visual notification of incoming text messages and other notifications from an **iPhone**.
- Improved software in **TuneIn**: more channels will work.
- Improved searching of points of interest (POI) in the navigation system.
- Performance and stability improvements to the infotainment system.
- The timing for the vehicle's approach lighting has changed: the old software was set to 30 seconds; the new software has it set to 120 seconds.