

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: COMMANDER SWITCH DOES NOT WORK	Service Alert No.: SA-025/19
	Last Issued: 06/12/2019

APPLICABLE MODEL(S)/VINS

2019 Mazda3 (Mexico built) with VINS starting with 3MZ

DESCRIPTION

On some vehicles, the Commander switch might be inoperative. This could be caused by fuse F13 (15A) being removed instead of F15 at the factory.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.