



# Technical Service Bulletin

---

<b>Technical Service Bulletin:</b> TSB190059	<b>Released Date:</b> 03-May-2019
<b>Water Pump Belt Squeal or Jump on Front End Accessory Drive</b>	

## Water Pump Belt Squeal or Jump on Front End Accessory Drive

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

#### Product Affected

Engine:

- B6.7 CM2350 B135B
- ISB6.7 CM2350 B103

Option:

- WP97431

#### Description of Change

A new water pump drive belt part number is now available.

#### Reason for Change

A shorter water pump drive belt was introduced to increase belt tension, reduce belt squeal, and belt jumping teeth on idler.

#### Service Instructions

When water pump drive belt service interval or malfunction occurs, use new water pump drive belt part number in Table 1 below.

See Table 1 below.

## Service Parts Availability

Service parts are available. See Table 1 for part numbers.

<b>Table 1, Service Parts</b>				
<b>Part Description</b>	<b>Existing Part Number</b>	<b>Obsolete</b>	<b>Superseded</b>	<b>New Part Number</b>
V, Ribbed Belt	4941303	No	No	4940003

## Production Status

Implemented for production. See Table 2.

<b>Table 2, Production Information</b>		
<b>ESN First</b>	<b>Build Date<sup>1</sup></b>	<b>Plant</b>
22326780	14 August 2018	Darlington Engine Plant
<sup>1</sup> Engine build date can be found on the engine dataplate.		

## Document History

<b>Date</b>	<b>Details</b>
2019-4-12	Module Created

---

**Last Modified: 03-May-2019**

---