



Supersession Statement

This PI was superseded to remove 2016 Chevrolet Volt. Please discard PIC5856E.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Customer comes in the dealer with a Check Engine Lamp with a current or history code P0C57, P0C58 and/or P0C62.

If you experience this concern and can't find a concern after checking wiring and following normal diagnosis, please replace the Motor B Position Sensor (Resolver) to resolve the concern.

After replacement of the Motor B Position Sensor (Resolver), make sure you check that the Drive Motor Generator Control Module (PIM) has the latest calibration.

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8466820	Drive Motor Position Sensor Stator Replacement	Use Published Labor Operation Time



GENERAL MOTORS