



# Preliminary Information

## PIP5579B Front and Rear Axle Restriction for Vehicles with RPO SU5 SU8 Has Ended

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	SU5 or SU8
Condition	Part restriction
Cause	New Product Monitoring

General Motors Technical Assistance Center part restriction on the front and rear axle assemblies (RPOs SU5 and SU8) for the 2019 Chevy Silverado 1500 (New Model) and 2019 GMC Sierra 1500 (New Model) has ended.

We would like to thank all dealers who participated in this restriction for their cooperation.

These Axle assemblies can now be repaired ordering parts through the regular GM CCA parts process and utilizing repair procedures covered in Service Information.

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the correct parts to order to perform the repairs as needed.

Parts Information

**Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the proper parts to repair as needed.**

Version History

Version	3
Modified	<p>08/08/2018 - Created on</p> <p>10/29/2018 - added part numbers <b>23243853, 84458156, 84454841, 23243766, 23243764, 84412729, 84459307, 84459322, 23243842, 23243845, 84459305, 84584310, 84412728, 84127132, 23243585, 11548535, 84443626, 84092759, 84092756, 23266134, 23243725</b></p> <p><b>06/24/2019 Updated to end restriction on parts and allowing full service.</b></p>



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.