



Preliminary Information

PIT5695 Brake Pad Life % Calculates Down too Quickly

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may notice a quick drop in the brake pad life % shown on the DIC, which may not be reflective to the actual pad wear.
Cause	This concern could be cause by a software anomaly.

Correction:

At this time, Do NOT perform any repairs. Engineering has identified the cause and is working toward a software solution, which will be released in the near future. When a repair becomes available, it will be published.

Version History

Version	1
Modified	06/28/2019 - Created on



GENERAL MOTORS