



# Service Bulletin

Bulletin No.: 19-NA-140

Date: June, 2019

## INFORMATION

**Subject:** Information on New Prop Shaft Replacement

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014	2019			6.2L (LT1, LT4, LT5)	

<b>Involved Region or Country</b>	North America, Russia, Europe, Middle East, Japan, Australia
<b>Condition</b>	Some customers may comment that they hear a rattle noise coming from the rear of the engine.
<b>Information</b>	<p><b>Note:</b> Additional repair information for a rattle noise can be found in Service Bulletin 18-NA-268. GM does not recommend replacing the complete driveline support assembly. The prop shaft can be replaced separately.</p> <p>If a noise was confirmed to be coming from the prop shaft, replace only the prop shaft instead of the complete driveline support assembly.</p>

### Parts Information

No parts are required for this repair.

<b>Version</b>	1
<b>Modified</b>	Released June 18, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION