

## **Service Bulletin**

Bulletin No.: 17-NA-350

Date: July, 2019

## **INFORMATION**

**Subject:** Information On Hitch Ball Movement on Gooseneck Drop-in Hitch

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado Models	2016	2018				
	Silverado 2500/3500	2019	2020				
GMC	Sierra Models	2016	2018				
	Sierra 2500/3500	2019	2020				

Involved Region or Country	North America, Middle East, South America, Israel and Thailand			
Additional Options (RPOs)	Z6A			
Condition	Some customers may comment that the gooseneck hitch ball has excessive movement in the hitch receiver after the ball has been locked in.			
Cause	This is a normal design of the hitch. Space must be provided between the hitch platform and hitch ball for corrosion and debris.			
Correction	No correction is necessary, hitch ball movement is normal and no parts should be replaced.  Please communicate to the customer this condition is a normal operating characteristic of their vehicle. Please share this information with the customer, including a copy of this			
	bulletin.			

## **Parts Information**

No parts are required for this repair.

Version	2
Modified	Released November 07, 2017 Revised July 08, 2019 - Added 2019 and 2020 models.

