ATTENTION:


GENERAL MANAGER

PARTS MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



© 2019 Subaru of America. Inc. All rights reserved.



SUBARU

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2018MY Crosstrek NUMBER: 06-72-19

SUBJECT: ABS Wheel Speed Sensor- Design Change DATE: 08/20/19

INTRODUCTION:

This Service Information Bulletin announces a design change to the ABS wheel speed sensor assemblies. The change optimizes moisture and corrosion resistance of the sensor harness casing.

PRODUCTION CHANGE INFORMATION:

The new ABS wheel speed sensor assemblies were incorporated into production starting with VIN JH221560.

PART INFORMATION:

Description	New Part Number
SENSOR ASSEMBLY-FRONT RIGHT	27540FL021
SENSOR ASSEMBLY-FRONT LEFT	27540FL031
SENSOR ASSEMBLY-REAR RIGHT	27540FL101
SENSOR ASSEMBLY-REAR LEFT	27540FL111

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedures for replacing the wheel speed sensors remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

Bulletin Number: 06-72-19; Date: 08/20/19

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 06-72-19; Date: 08/20/19 Page 2 of 2