



Bulletin No.: PIP5728B
Published date: 06/1/2020

Preliminary Information

PIP5728B Fuel Pump Driver Control Module Configuration Function Missing in GDS2

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado HD	2020	All	All	6.6L L8T	All
GMC	Sierra HD	2020	All	All	6.6L L8T	All

Involved Region or Country	North America
Condition	When instructed by Service Information to perform "Fuel Pump Driver Control Module Configuration" after fuel pump driver control module replacement, it may be found that this function is missing in GDS2.
Cause	GDS2 Software

Correction:

A software update for GDS2 has been released to correct the missing Fuel Pump Driver Control Module Configuration function.

Ensure GDS2 software and diagnostic package are updated to the latest version.

Version History

Version	3
Modified	05/12/2020 - Created on. 05/27/2020 - Update to Correction information. 06/01/2020 - Update to Models



GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.