

**ATTENTION:**

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.


© 2020 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2012-20MY Impreza  
 2017-20MY Crosstrek  
 2013-20MY BRZ  
 2010-20MY Legacy  
 2014-20MY Forester  
 2015-20MY WRX & STI  
 2019-20MY Ascent

**NUMBER:** 18-201-20

**DATE:** 10/02/20

**SUBJECT:** Service Manual Corrections

### INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2012	Impreza	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	The illustration was changed and a caution was added

**CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

**Subaru of America, Inc. is ISO 14001 Compliant**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2013	Impreza	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
			Airbag System	Diagnostic Chart With Trouble Code >DTCs B19F0 B19F1 B19F2 & B19F3	Some descriptions were changed to the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	The illustration was changed and a caution was added
2014	Impreza	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
			Airbag System	Diagnostic Chart With Trouble Code >DTCs B19F0 B19F1 B19F2 & B19F3	Some descriptions were changed to the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	The illustration was changed and a caution was added
2015	Impreza	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
			Airbag System	Diagnostic Chart With Trouble Code >DTCs B19F0 B19F1 B19F2 & B19F3	Some descriptions were changed to the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	The illustration was changed and a caution was added
2016	Impreza	Transmission /Transaxle	CVT	General Description >Preparation Tool	A SST illustration was added
				Control Valve Body >Removal & Installation	Some descriptions and illustrations were added
		Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Airbag System	Diagnostic Chart With Trouble Code >DTCs B19F0 B19F1 B19F2 & B19F3	Some descriptions were changed to the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	The illustration was changed and a caution was added

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2017	Impreza	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Brake Control	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			Airbag System	Diagnostic Procedure w/ DTC >B1698	A description in step 2 of the trouble tree was changed
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
			Airbag System	Diagnostic Chart With Trouble Code >DTCs B19F0 B19F1 B19F2 & B19F3	Some descriptions were changed to the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration and descriptions were changed
				Roof Rail >Removal & Installation	The illustration was changed and descriptions were added
		Engine	Fuel Injection	General Description >Component	An illustration was changed and descriptions were added for the engine wiring harness
				Intake Manifold Assembly >Removal & Installation	Descriptions and illustrations were changed and added
		2018	Impreza/ Crosstrek	Diagnostics	BSD/RCTA
Brake Control	Diagnostic Procedure w/ DTC >C1531				Some descriptions were changed in the trouble tree
Airbag System	Diagnostic Procedure w/ DTC >B1698				A description in step 2 of the trouble tree was changed
Lan System	Basic Diagnostic Procedure >Procedure				A description was changed
Airbag System	Diagnostic Chart With Trouble Code >DTCs B19F0 B19F1 B19F2 & B19F3				Some descriptions were changed to the trouble trees for these DTCs
Body & Electrical/ Wiring System	Exterior/Interior Trim			General Description >Component	The roof rail illustration and descriptions were changed
				Roof Rail >Removal & Installation	The illustration was changed and descriptions were added
Engine	Fuel Injection			General Description >Component	An illustration was changed and descriptions were added for the engine wiring harness
				Intake Manifold Assembly >Removal & Installation	Descriptions and illustrations were changed and added

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2019	Impreza/ Crosstrek	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Eyesight	Lane Departure Prevention Assist Deactivate Code Display	A description was added
			Electric Brake Booster	General Description >Caution	Some descriptions were changed in the initial learning procedure
				Work Support >List	Some descriptions were changed
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Telematics	Diagnostic Procedure w/ DTC >DTC B2A16	The trouble tree procedure was changed	
		Brakes	Brake	General Description >Specification	Some procedures, specifications and descriptions were changed, deleted and added
			VDC	VDCCM&H/U >Removal & Installation	A removal step was added and the installation procedure changed
				VDCCM&H/U >Inspection	Some inspection steps were changed and added
		General Description	PDI	PDI Procedure >Brake Fluid	An illustration and some descriptions were changed
		Engine	Fuel Injection	General Description >Component	An illustration was changed and descriptions were added for the engine wiring harness
				Intake Manifold Assembly >Removal & Installation	Descriptions and illustrations were changed and added
		2020 (cont.)	Impreza/ Crosstrek	Brakes	Brake
VDC	VDCCM&H/U >Removal & Installation				Some descriptions were changed, deleted and added
	VDCCM&H/U >Inspection				Some inspection steps were changed and added
Diagnostics	Eyesight			Lane Departure Prevention Assist Deactivate Code Display	A description was added
	Electric Brake Booster			General Description >Caution	Some descriptions were changed in the initial learning procedure
				Work Support >List	Some descriptions were changed
	Lan System			Basic Diagnostic Procedure >Procedure	A description was changed
Telematics	Diagnostic Procedure w/ DTC >DTC B2A16	The trouble tree procedure was changed			

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2020	Impreza/ Crosstrek	General Description	Precaution / Warning	Warning (Hybrid System) >Precautions for Maint., Service Disconnect Plug & Moving the Damaged Vehicle	Some cautions and procedures were changed
				Caution >Active Grill Shutter & Airbag	Some descriptions were changed
			PDI	PDI Procedure >Brake Fluid	An illustration and some descriptions were changed
2013	BRZ	Manual Transmission/ Transaxle	Neutral Position Switch	Inspection	The standard resistance values of the neutral position switch were changed
		Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2014	BRZ	Manual Transmission/ Transaxle	Neutral Position Switch	Inspection	The standard resistance values of the neutral position switch were changed
		Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2015	BRZ	Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2016	BRZ	Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2017	BRZ	Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2018	BRZ	Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2019	BRZ	Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2020	BRZ	Drive Shaft/ Propellar Shaft	Rear Drive Shaft Assy	Exploded View & Assembly	An illustration was changed and some descriptions were changed and added
		Preparation Items	Drive Shaft/ Propellar Shaft	Lubricant, Etc.	The lubricant descriptions of use were changed and added
2010	Legacy	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
2011	Legacy	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
2012	Legacy	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
2013	Legacy	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-7)	Some descriptions were changed in the trouble trees for these DTCs
2014	Legacy	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-7)	Some descriptions were changed in the trouble trees for these DTCs
2015	Legacy	Brakes	Brake	General Description >Component	T3 spec was changed for front disc brake illustration
		Diagnostics	VDC	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration and descriptions were changed
Roof Rail >Removal & Installation	Some illustrations were changed and a caution was added				
2016	Legacy	Diagnostics	VDC	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
			BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2017	Legacy	Diagnostics	VDC	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added
2018	Legacy	Diagnostics	VDC	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added and deleted
2019	Legacy	Diagnostics	VDC	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added and deleted
2020	Legacy	Body & Electrical/ Wiring System	Wiring System	CVT Control System >Wiring Diagram	Wiring diagram 2D was changed
		Diagnostics	Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
				DTC >List	A description was deleted and an illustration was changed
				Diagnostic Procedure w/ DTC >DTC U115B	A procedure of U115B was deleted
		Telematics	Diagnostic Procedure w/ DTC >DTC B2A16 & U115B	The trouble tree procedure was changed	

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2014	Forester	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2762	The trouble tree procedure was changed
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added
2015	Forester	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added
2016	Forester	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added
2017	Forester	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
				Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added
2018	Forester	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
		Body & Electrical/ Wiring System	Exterior/Interior Trim	Roof Rail >Removal & Installation	Some illustrations were changed a torque spec was changed and a caution was added
2019 (cont.)	Forester	Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration was changed and the descriptions were added
			Seats	Front Seat >Removal	Some descriptions were deleted and added
		Power Seat System >Removal		Some descriptions were added and changed	
		Power Seat System >Inspection		Some changes were made to the symptom table and procedures	

*Continued...*



YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2019	Forester	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Eyesight	Lane Departure Prevention Assist Deactivate Code Display	A description was added
			Brake Control	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
			Telematics	Diagnostic Procedure w/ DTC >DTC B2A16	The trouble tree procedure was changed
			Power Rear Gate	Diagnostic Procedure w/ DTC >B2524	Pinpoint tests were changed in trouble tree steps 3 and 4
		General Description	Recommended Materials	Refrigerant	The recommended compressor oil was changed
	Airbag System & Seatbelt System	Airbag System	General Description >Component	Some descriptions were changed and deleted	
2020	Forester	Body & Electrical/ Wiring System	Seats	Front Seat >Removal	Some descriptions were deleted and added
				Power Seat System >Removal	Some descriptions were added and changed
				Power Seat System >Inspection	Some changes were made to the symptom table and procedures
		Diagnostics	Brake Control	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			Eyesight	Lane Departure Prevention Assist Deactivate Code Display	A description was added
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
			Telematics	Diagnostic Procedure w/ DTC >DTC B2A16	The trouble tree procedure was changed
	Power Rear Gate	Diagnostic Procedure w/ DTC >B2524	Pinpoint tests were changed in trouble tree steps 3 and 4		
2015	WRX / STI	Diagnostics	CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)	Some descriptions were changed in the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Ligthing System	Rear Combination Light Assembly >Removal & Installation	An illustration was added and some descriptions were changed and added

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2016	WRX / STI	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			CVT	Diagnostic Procedure w/ DTC >P2757 & P2758	Some descriptions were changed in the trouble trees for these DTCs
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)	Some descriptions were changed in the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Ligthing System	Rear Combination Light Assembly >Removal & Installation	An illustration was added and some descriptions were changed and added
2017	WRX / STI	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)	Some descriptions were changed in the trouble trees for these DTCs
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Engine	Mechanical	Engine Assembly >Removal & Installation	Some descriptions were added
				Rocker Cover >Removal & Installation	Some descriptions were added
			Cooling	Water Pipe Assembly >Removal & Installation	Some descriptions were added
			Lubrication	Oil Pan >Removal & Installation	Some descriptions were added
				Oil Level Switch >Removal & Installation	Some descriptions were added
		Body & Electrical/ Wiring System	Ligthing System	Rear Combination Light Assembly >Removal & Installation	An illustration was added and some descriptions were changed and added
		2018 (cont.)	WRX / STI	Diagnostics	BSD/RCTA
Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)				Some descriptions were changed in the trouble trees for these DTCs
Lan System	Basic Diagnostic Procedure >Procedure				A description was changed
Body & Electrical/ Wiring System	Ligthing System			Rear Combination Light Assembly >Removal & Installation	An illustration was added and some descriptions were changed and added

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2018	WRX / STI	Engine	Mechanical	Rocker Cover >Removal & Installation	Some descriptions were added
				Engine Assembly >Removal & Installation	Some descriptions were added
			Cooling	Water Pipe Assembly >Removal & Installation	Some descriptions were added
			Lubrication	Oil Pan >Removal & Installation	Some descriptions were added
				Oil Level Switch >Removal & Installation	Some descriptions were added
2019	WRX / STI	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)	Some descriptions were changed in the trouble trees for these DTCs
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Engine	Mechanical	Engine Assembly >Removal & Installation	Some descriptions were added
				Rocker Cover >Removal & Installation	Some descriptions were added
			Cooling	Water Pipe Assembly >Removal & Installation	Some descriptions were added
			Lubrication	Oil Pan >Removal & Installation	Some descriptions were added
				Oil Level Switch >Removal & Installation	Some descriptions were added
		Body & Electrical/ Wiring System	Ligthing System	Rear Combination Light Assembly >Removal & Installation	An illustration was added and some descriptions were changed and added
		2020	WRX / STI	Diagnostics	Lan System
Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)				Some descriptions were changed in the trouble trees for these DTCs

*Continued...*

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2017	Crosstrek	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
			Airbag System	Diagnostic Chart w/ Trouble Code >DTC B19F(0-3)	Some descriptions were changed in the trouble trees for these DTCs
		Body & Electrical/ Wiring System	Exterior/Interior Trim	General Description >Component	The roof rail illustration and descriptions were changed
				Roof Rail >Removal & Installation	The illustration was changed and descriptions were added
2019	Ascent	Diagnostics	BSD/RCTA	Diagnostic Procedure w/ DTC >B2350	A change was made to step 6 of the trouble tree
			Brake Control	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
			Telematics	Diagnostic Procedure w/ DTC >B2A16	The trouble tree procedure was changed
		Power Rear Gate	Diagnostic Procedure w/ DTC >B2524	Pinpoint tests were changed in trouble tree steps 3 and 4	
		Body & Electrical/ Wiring System	Ligthing System	Rear Combination Light Assembly >Installation	The tightening tourqe was added
			Sunroof/ T-Top/ Convertible Top	Sunroof Control System >Operation	The initialization and reinitialization procedures were changed
			Wiring System	CVT Control System >Wiring Diagram	Wiring diagram e was changed.
2020	Ascent	Diagnostics	Brake Control	Diagnostic Procedure w/ DTC >C1531	Some descriptions were changed in the trouble tree
			Telematics	Diagnostic Procedure w/ DTC >B2A16	The trouble tree procedure was changed
			Power Rear Gate	Diagnostic Procedure w/ DTC >B2524	Pinpoint tests were changed in trouble tree steps 3 and 4
			Lan System	Basic Diagnostic Procedure >Procedure	A description was changed
		Body & Electrical/ Wiring System	Sunroof/ T-Top/ Convertible Top	Sunroof Control System >Operation	The initialization and reinitialization procedures were changed
			Ligthing System	Rear Combination Light Assembly >Installation	The tightening tourqe was added
			Wiring System	CVT Control System >Wiring Diagram	Wiring diagram e was changed.