
ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

SUBJECT:

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



QUALITY DRIVEN® SERVICE

SUBARU

NUMBER: 07-89-15R DATE: 02-10-15

REVISED: 08-23-16

 $\hbox{@\,}2015$ Subaru of America, Inc. All rights reserved.

SERVICE INFORMATION

APPLICABILITY: 2015-16MY Legacy and Outback Models

Interior Fuse Box (F/B) "IG" and "ACC" Relay

Under-Hood Fuse Box (M/B) Main Relay

Replacement for Engine Will Not Crank / Start Condition

NOTE: As of 8/23/2016, this TSB has been replaced with Service Program Bulletins WTG-67 and WTH-68. Please refer to those publications for the most updated information relating to the repairs originally contained in TSB 07-89-15R.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.