

Service Bulletin

Bulletin No.: 17-NA-114


Date: October, 2020

TECHNICAL

Subject: Oil Leak from Turbocharger Inlet or Outlet Duct

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Colorado	2016	2021				
	Express	2017				LWN	
GMC	Canyon	2016				LVVIN	
	Savana	2017					

Involved Region or Country	North America, Middle East, Israel, Palestine, GM Korea Company		
Additional Options (RPOs)	Equipped with Diesel Engine (RPO LWN)		
Condition			
	4754826		



Parts Information

No parts are needed for this concern.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time	
4081608*	Tighten the Charge Air Cooler Duct Clamp	0.4 hr	
*This is a unique Labor Operation for Bulletin use only.			

Service Procedure

Refer to Charge Air Cooler Inlet/Outlet Duct Replacement in SI for the procedure to gain access to the clamps needed to be tightened.

Version	5		
	Released April 13, 2017		
	Revised August 29, 2017 — Added 2018 Model Year.		
Modified	Revised July 23, 2018 – Added 2019 Model Year.		
Modified	Revised September 19, 2019 – Added 2020 Model Year.		
	Revised October 21, 2020 - Added 2021 Model Year and removed 2016 from Express and Savana.		