

Subject: Engineering Information – Leak from Transmission Front Input Shaft Seal and/or Rear Main Shaft Seal

This EI has been revised to end the need for information from the field. Please discard PIE0561.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2020	—	—	Equipped with 2.0L or 3.6L Engine (RPOs LTG, LGX)	Equipped with 6-Speed Manual Transmission (RPO M13)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released March 20, 2020 October 02, 2020 – Ended the need for further information from the field.