

Published date: 11/17/2020

Preliminary Information

PIT5797 Hands Free Liftgate Feature Inoperative After Vehicle Has Gone To Sleep

Models

| Brand: | Model: | Model Years: | VIN: | | Engine | Transmissions: |
|-----------|--------------|--------------|------|-----|---------|----------------|
| | | | from | to | Engine: | Transmissions. |
| Chevrolet | Suburban | 2021 | All | All | All | All |
| Chevrolet | Tahoe | 2021 | All | All | All | All |
| GMC | Yukon Models | 2021 | All | All | All | All |

| Involved Region or Country | North America | |
|----------------------------|---|--|
| Condition | Some customers may comment that when they try to use the hands free liftgate feature after the ignition has been turned off for a period of time, it is found to be inoperative. If they use the button on the RKE Fob, liftgate, or overhead console, the liftgate will operate. After it has operated for the first time, then the hands free feature will begin to work again until the vehicle sits for another period of time. | |
| Cause | This concern could be caused by a BCM software issue. | |

Correction:

To correct this issue, reprogram the BCM with the latest calibrations in Tis2Web.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time | | |
|--|--|--------------------|--|--|
| 2810215 | Body Control Module Reprogramming with SPS | Use published time | | |
| *This is a unique Labor Operation for Bulletin use only. | | | | |

Version History

| Version | 1 |
|----------|--------------------------|
| Modified | 11/17/2020 - Created on. |

















GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.