

Subject: Engineering Information - Request for Pictures On Rear View Camera Not Aligned Customer Concerns

This PI has been revised to end the need for information from the field. Please discard PIE0589.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2020	2020	-	-	-	-

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 15, 2020 Revised November 30, 2020 – Ended the need for further information from the field.