

Subject: Engineering Information - Intermittent No Start

This PI has been revised to end the need for information from the field. Please discard PIE0594.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500/3500 HD	2020	2021	-	-	Equipped with 6.6L Engine (RPO L8T)	-
GMC	Sierra 2500/3500 HD						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 23, 2020 Revised November 04, 2020 – Ended the need for further information from the field.