



Bulletin No.: PIT5789A

Published date: N/A

Preliminary Information

PIT5789A SES MIL DTC P2B87

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2021	All	All	L87	All
Chevrolet	Silverado 1500	2021	All	All	L84 or L87	All
Chevrolet	Suburban	2021	All	All	L84 or L87	All
Chevrolet	Tahoe	2021	All	All	L84 or L87	All
GMC	Sierra 1500	2021	All	All	L84 or L87	All
GMC	Yukon Models	2021	All	All	L84 or L87	All

Involved Region or Country	North America
Condition	Some customer may comment on an SES MIL and when DTC's are checked, a P2B87 may be set. The customer will not have any additional symptoms, other than the SES MIL.
Cause	Engineering is currently working on releasing updated BCM calibrations for this concern.

Correction:

At this time, do NOT replace the G17 Heater Coolant Pump as this will not correct this concern. Clear the DTC's and advise the customer new calibrations will be released shortly to correct the issue. This PI will be updated when the calibrations are released.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*4486068	Scan for DTC's and Clear	0.3 HR.

*This is a unique Labor Operation for Bulletin use only.

Version History

Version	2
Modified	10/29/2020 - Created on. 12/03/2020- Updated the model list



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.