

Published date: 12/27/2020

# **Preliminary Information**

# PIT5804 SES MIL DTC P2B87

#### Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Hansinissions.
Buick	Enclave	2021	All	All	All	All
Cadillac	XT5	2021	All	All	All	All
Cadillac	XT6	2021	All	All	All	All
Chevrolet	Blazer	2021	All	All	All	All
Chevrolet	Traverse	2021	All	All	All	All
GMC	Acadia	2021	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on an SES MIL and when DTC's are checked, a P2B87 may be set. The customer will not have any additional symptoms, other than the SES MIL.
Cause	Engineering is currently working on releasing updated BCM calibrations for this concern.

#### **Correction:**

At this time, do NOT replace the G17 Heater Coolant Pump as this will not correct this concern.

Clear the DTC's and advise the customer new calibrations will be released shortly to correct the issue.

This PI will be updated when the calibrations are released.

### **Warranty Information**

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time		
*4486068	Scan for DTC's and Clear	0.3 HR.		
*This is a unique Labor Operation for Bulletin use only.				

## Additional SI Keywords

aux, auxiliary, code, coolant, HVAC, light, speed,

## **Version History**

Version	1
Modified	PIT5804 created 12/21/2020

















# GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.