

Service Bulletin

INFORMATION

Subject:	Information on Possible Normal Engine Noise
----------	---

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission.
Buick	Encore GX	2020	2021			1.2L Turbo	
Chevrolet	Trailblazer (VIN M)	2021		—	—	(RPO LIH)	—

Involved Region or Country	North America			
Condition	Some customers may comment that the engine makes noises that do not seem normal.			
Information	The LIH engine in the Buick Encore GX and Chevrolet Trailblazer may exhibit a noise that is noticeable or possibly objectionable to the customer under certain circumstances. The noise sounds like a deep thudding in the engine when it is operating in the lower speed range (typically less than 2,000 rpm) during a launch at moderate to high throttle inputs. This noise may be more pronounced when the engine is cold, than once it has warmed up. This noise is inherent to this small-displacement, power-dense engine design. Customers who experience this noise and express concern about it should be reassured that this is not an indication that anything is wrong with their engine. The attached recording provides an example of this noise condition, which is considered normal, and for which the customer should have no concern.			

Parts Information

No parts are required for this repair.

Version	2
Modified	Released April 06, 2020 December 11, 2020 - Added the 2021 Model Year to the Encore GX.

