



# Service Bulletin

Bulletin No.: 20-NA-114

Date: December, 2020

## INFORMATION

**Subject:** Information on False Setting of DTC U0212

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4	2020	2020			All	All
	CT5						
	Escalade	2021	2021				
	Escalade ESV						
Chevrolet	Corvette (Middle East Export Only)	2020	2020				
	Suburban	2021	2021				
	Tahoe						
GMC	Yukon	2021	2021				
	Yukon XL						

<b>Involved Region or Country</b>	North America, China, Europe, Cadillac Korea (South Korea), Middle East
<b>Additional Options (RPOs)</b>	Vehicles equipped with STEERING COLUMN LOCK-ELECTRICAL (N06)
<b>Condition</b>	Technicians may find DTC U0212 set in the IPC, BCM or CGM.
<b>Cause</b>	The cause of the condition may be that DTC U0212 is a false reading that mapped incorrectly on vehicles equipped with RPO N06.
<b>Correction</b>	Technician is to ignore DTC U0212 setting and diagnose as DTC U0236.

### Parts Information

No parts are normally required for this repair.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
7485998*	Diagnose as DTC U0236	0.3 hr

\*This is a unique Labor Operation for Bulletin use only.

<b>Version</b>	2
<b>Modified</b>	Released May 26, 2020 Revised December 04, 2020 – Added Corvette and SUV Models, and Added Warranty Information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION