

Subject: Engineering Information – Lane Keep Assist/ Forward Collision Alert (if equipped) /Adaptive Cruise Control Inoperativ and Requires Front Camera Module to be Reprogrammed/Aligned or Replaced, DTCs B101E, B395D and/or U026A Set

This EI has been revised to end the need for information from the field. Please discard PIE0565A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020	2020	—	—	—	—

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released April 16, 2020 June 25, 2020 – Updated the Subject and the Condition section. December 21, 2020 – Ended the need for further information from the field.