

Subject: Engineering Information – Request for Pictures on Factory Installed (RPO DNS) Hood Wrap or Stripe Concern

This EI has been revised to end the need for information from the field. Please discard PIE0585.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2020	2021	Built After January 1, 2020	—	—	—

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released September 25, 2020 December 04, 2020 – Ended the need for further information from the field.