



Preliminary Information

PIP5799 10L60 10L80 10L90 10L1000 Automatic Transmissions With SES Light And DTCs P2812 or P2814 Setting

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2020 - 2021	All	All	All	MQA
Cadillac	CT5	2020 - 2021	All	All	All	MHS
Cadillac	CT6	2019 - 2020	All	All	All	MHS MHW
Cadillac	Escalade Models	2019 - 2021	All	All	All	MF6 MQC
Chevrolet	Camaro	2019 - 2021	All	All	All	MF6 MGL MI1 MI2 MI3 MI4
Chevrolet	Silverado 1500 New Model	2019	All	All	All	MQB
Chevrolet	Silverado 1500	2020 - 2021	All	All	All	MQB
Chevrolet	Suburban	2019 - 2021	All	All	All	MF6 MQC
Chevrolet	Tahoe	2019 - 2021	All	All	All	MF6 MQC
GMC	Sierra 1500 New Model	2019	All	All	All	MQB
GMC	Sierra 1500	2020 - 2021	All	All	All	MQB
GMC	Yukon Models	2019 - 2021	All	All	All	MF6 MQC

Involved Region or Country	North America
Condition	Customers may comment on an illuminated check engine light and their transmission shifts harsh. Technicians may find code P2812 or P2814 set in the TCM.
Cause	Electrical fault in Transmission Control Solenoid Valve 7 (Line Pressure Solenoid).

Correction:

If following SI diagnostics does not lead to root cause of the P2812 or P2814 DTCs setting the valve body should be replaced.

Warranty Information

Version History

Version	1
Modified	04/01/2021 - Created on.



© 2021 General Motors. All Rights Reserved.