



Preliminary Information

PIP5788A DTC P2635 Set

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|----------------|--------------|------|-----|---------------------|----------------|
| | | | from | to | | |
| Chevrolet | Silverado 1500 | 2021 | All | All | 5.3 L82 L84 6.2 L87 | All |
| GMC | Sierra 1500 | 2021 | All | All | 5.3 L82 L84 6.2 L87 | All |

| | |
|----------------------------|---|
| Involved Region or Country | North America |
| Condition | Some customers may comment that the SES lamp is illuminated or was illuminated and turned off, with no drivability concerns. During inspection Technician may notice DTC P2635. |
| Cause | Unknown at this time |

Correction:

If you encounter a vehicle with the above DTC, follow the applicable diagnostic flow chart in service information for further diagnosis and repair.

If the diagnostic does not isolate the concern, replace fuel feed pipe (fuel line between the high-pressure fuel pump and chassis line), clear the codes, and return it to the customer.

If the truck has already had the fuel jumper replaced, do not replace again. Follow diagnostic flow chart to ensure a different issue has not developed.

If it does not isolate the concern, clear codes only and return to the custom.

Engineering knows about the concern and is working on a more permanent service procedure.

This PI will be updated as information is gathered.

Version History

| | |
|----------|---|
| Version | 1 |
| Modified | 03/16/2021 - Created on. 04/15/2021 - updated the correction statement |

