

ATTENTION:

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2021 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2019-21MY Ascent
SUBJECT: Service Manual Corrections

NUMBER: 18-208-21
DATE: 05/05/21

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2021	Ascent	Diagnostics	Tire Pressure Monitor	Diagnostic Procedure with Diagnostic Trouble Code	Diagnostic stepd changed for DTC C2921.
			Engine (H4DOTC)	Diagnostic procedure with DTC.	Diagnostic steps added for DTCs P0011, 0014, 0021, 0024.
		Engine	Speed Control (H4DOTC)	Accelerator Pedal	Inspection/testing steps added.
			Fuel Injection (H4DOTC)	Throttle Body	Inspection/testing steps added.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE		
2020	Ascent	Engine	Speed Control (H4DOTC)	Accelerator Pedal	Inspection/testing steps added.		
			Fuel Injection (H4DOTC)	Throttle Body	Inspection/testing steps added.		
		Heater & Air Conditioner/ Ventilation	Air Conditioner	Heater & Cooling Unit Rear	Removal and Installation steps have been changed.		
		Diagnosis	Engine (H4DOTC)	Diagnostic procedure with DTC.	Diagnostic steps added for DTCs P0011, 0014, 0021, 0024.		
			Power Rear Gate	Diagnostic procedure with DTC.	Diagnostic steps changed for DTC B2524.		
			Telematics	Diagnostic procedure with DTC.	Diagnostic steps changed for DTC B2A16.		
		Brakes	Front Brake Pad	Installation	Steps changed to include the Brake Pad Assembly Grease.		
			Front Disc Brake Assembly	Installation	Steps changed to include the Brake Pad Assembly Grease.		
			Rear Brake Pad	Installation	Steps changed to include the Brake Pad Assembly Grease.		
			Rear Disc Brake Assembly	Installation	Steps changed to include the Brake Pad Assembly Grease.		
		Body & Electrical / Wiring System	Tire Pressure Monitor	Diagnostic Procedure with Diagnostic Trouble Code	Diagnostic steps changed for DTC C2921.		
			Wiring System	CVT Control System	CVT Control System Wiring Diagram has been changed.		
		2019	Ascent	Engine	Speed Control (H4DOTC)	Accelerator Pedal	Inspection/testing steps added.
					Fuel Injection (H4DOTC)	Throttle Body	Inspection/testing steps added.
Heater & Air Conditioner/ Ventilation	Air Conditioner			Heater & Cooling Unit Rear	Removal and Installation steps have been changed.		
Diagnosis	Engine (H4DOTC)			Diagnostic procedure with DTC.	Diagnostic steps added for DTCs P0011, 0014, 0021, 0024.		
	Power Rear Gate			Diagnostic procedure with DTC.	Diagnostic steps changed for DTC B2524.		
	Telematics			Diagnostic procedure with DTC.	Diagnostic steps changed for DTC B2A16.		
Brakes	Front Brake Pad			Installation	Steps changed to include the Brake Pad Assembly Grease.		
	Front Disc Brake Assembly			Installation	Steps changed to include the Brake Pad Assembly Grease.		
	Rear Brake Pad			Installation	Steps changed to include the Brake Pad Assembly Grease.		
	Rear Disc Brake Assembly			Installation	Steps changed to include the Brake Pad Assembly Grease.		
Body & Electrical / Wiring System	Tire Pressure Monitor			Diagnostic Procedure with Diagnostic Trouble Code	Diagnostic steps changed for DTC C2921.		
	Wiring System			CVT Control System	CVT Control System Wiring Diagram has been changed.		