


Preliminary Information

PIT5866 Home Screen Bar missing on left side of Integrated Center Stack (ICS)


Models

Brand:	Model:	Model Years:	VIN:		Engino	Transmissions:
			from	to	Engine:	Transmissions.
Chevrolet	Suburban	2022	All	All	All	All
Chevrolet	Tahoe	2022	All	All	All	All
GMC	Yukon	2022	All	All	All	All
GMC	Yukon XL	2022	All	All	All	All

Involved Region or Country	United States, Canada, Mexico		
Additional Options (RPO)	юк		
Condition	Customers will notice that the home screen bar is missing on the left side of the display.		
	EX. Defect		



EX. Working



Cause

Condition is occurring in W160.4 software and reason is unknown at this time.

Correction:

General Motors Engineering is investigating the concern and once a repair is available this PI will be updated. Please do not replace any parts for this issue

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time		
3487488	Inspect for concern	0.2 Hr.		
*This is a unique Labor Operation for Bulletin use only.				

Version History

Version	1	
Modified	11/09/2021 - Created on.	

















GENERAL MOTORS

 $\hbox{@ 2021 General Motors.}$ All Rights Reserved.