

Preliminary Information

PIT5849C Tail Lights Remain On After Passive Locking and/or Dead Battery

Product Investigation Review Required

<u>Models</u>

Brandt	Model:		Model Years:	VIN:		Engine	Transmissions:	
Brand:				from	to	Engine:	Transmissions.	
Chevrolet	Silverado 2500HD/3500HD		2022	All	All	All	All	
GMC	Sierra 2500HD/3500HD		2022	All	All	All	All	
Involved Persion or Country								
Involved Region or Country		North America						
Condition		Some customers may comment that the rear tail / parking lights stay on and do not time out after exiting the vehicle and passive locking the vehicle. This condition can lead to a dead battery.						
Cause		The cause of this condition is a BCM Software issue.						

Correction:

To correct this concern perform Customer Satisfaction Program N212344990 "Turn Signals Remain On After Passive Door Locking".

In some rare cases, a vehicle may have the same symptoms as listed in N212344990, but the vehicle is not involved in the customer satisfaction program. If the BCM has the latest calibration and still exhibits the concern, then GM Engineering is working on a fix. Because this condition only occurs if passive locking is used please turn off passive locking in vehicle settings until a fix is released. Also, Please submit a Field Product Report (FPR) following bulletin 02-00-89-002T.

Additional SI Keywords

Park left right lamps lamp lighting light taillight taillamp

Version History

Version	4
	07/26/2021 - Created on.
Modified	09/23/2021 - Updated to remove the light duty trucks.
Modified	10/28/2021 - Updated the correction
	11/29/2021 - Updated the correction.



© 2021 General Motors. All Rights Reserved.