



Preliminary Information

PIC6448 Diagnostic Tip - T6 PIM /HPCM Programing

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2016 - 2019	All	All	ALL	ALL
Chevrolet	Volt	2016 - 2019	All	All	ALL	ALL

Involved Region or Country	North America
Condition	SPS 2 may not program the T6 PIM Module
Cause	Possible Techline Connect has a Software issue

Correction:

Please Call Techline so they Can help get the T6 PIM / HPCM programed.

TCSC: 1-800-828-6860 English or 1-800-503-3222 French, 8am-8pm (EST) Monday through Saturday

Provide them with the SI document and let them know if you replaced the module or trying to update it.

They may ask for a part# for the module or the Transmission.

Techline will Work with you to get temporary Access to SPS1 for Programing this module.

Version History

Version	1
Modified	11/29/2021 - Created on.



GENERAL MOTORS