



TECHNICAL SERVICE BULLETIN

2.7L - Cannot Disable Traction Control From The Traction Control Switch - Built On Or Before 14-Mar-2022

22-2255

28 June 2022

Model:

Ford 2021-2022 Bronco	Engine: 2.7L Built on or before 14-Mar-2022
---------------------------------	--

Issue: Some 2021-2022 Bronco vehicles built on or before 14-Mar-2022 and equipped with a 2.7L engine may exhibit the inability to disable the traction control system using the traction control on/off switch located on the instrument panel. This may be due to the software within the anti-lock brake system (ABS) module. To correct the condition, follow the Service Procedure to update the ABS software.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2021-2022 Bronco
- Built on or before 14-Mar-2022
- Equipped with a 2.7L engine
- Unable to disable the traction control system using the traction control on/off switch located on the instrument panel

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2021-2022 Bronco 2.7L: Reprogram The ABS Module (Do Not Use With Any Other Labor Operations)	MT222255	Actual Time

Repair/Claim Coding

Causal Part:	2C219
Condition Code:	04

Service Procedure

1. Reprogram the ABS module using the latest software level of the Ford Diagnosis and Repair System (FDRS) scan tool.

© 2022 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.