



Preliminary Information

PIT5942 Information On Vehicle Option Retrofits Due to The Chip Shortage.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XT4	2022	All	All	All	All
Cadillac	XT5	2022	All	All	All	All
Cadillac	XT6	2022	All	All	All	All
Chevrolet	Equinox	2022	All	All	All	All
Chevrolet	Malibu	2022	All	All	All	All
GMC	Acadia	2022	All	All	All	All
GMC	Terrain	2022	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	00R, 00V, 00Z, 04O
Condition:	Cannot complete or program component retrofit.
Cause:	Retrofit for your particular vehicle may not be released yet.

Correction:

TAC is receiving calls for assistance on retrofits not yet released .

The Heated Vented Seat retrofit will be executed under six separate bulletins (N212354520 to N212354525).

These are being launched based on parts availability, trim level and model.

If you are presented a vehicle for retrofit and there is not an open bulletin listed in VIS for this vehicle VIN do NOT attempt the retrofit.

You may not receive the correct components and will not be able to program them.

Version History

Version	1
Modified	9/8/2022 - Created



GENERAL MOTORS