



Preliminary Information

PIT5936C Headlights On During Daylight Condition DTC B108E

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2022	All	All	All	All
Chevrolet	Suburban	2022	All	All	All	All
Chevrolet	Tahoe	2022	All	All	All	All
GMC	HUMMER EV	2022	All	All	All	All
GMC	Yukon Models	2022	All	All	All	All

Involved Region or Country	North America, Europe, Kazakhstan, Uzbekistan, Russia, Middle East, Israel, Palestine, Bolivia, Chile, Columbia, Ecuador, Peru, Japan, S. Korea, Thailand
Condition	Some customers may notice during daylight conditions that the Daytime Running Lamps (DRL's) are not on and that the low beam headlamps are on. Upon further inspection, technicians may find a DTC B108E set for the Ambient Light Sensor signal.
Cause	The cause of this condition could be an issue with the BCM calibration.

Correction:

GM engineering has released new updated BCM calibrations to address this issue. To correct this condition, reprogram the BCM with the latest calibrations available in Service Programming Systems (SPS).

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

Version History

Version	4
Modified	08/03/2022 - Created on. 08/11/2022 - Update to the Cause, Correction and Warranty sections. 09/23/2022 - Updated to add the HUMMER EV to the models. 09/26/2022 - Updated the Involved Region/Country



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.