



# Preliminary Information

## PIT5917A No Selection In The DIC To Reset The Fuel Filter Life (Canada and Mexico Vehicles Only)

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Suburban	2021 - 2022	All	All	3.0L LM2	All
Chevrolet	Tahoe	2021 - 2022	All	All	3.0L LM2	All
GMC	Yukon Models	2021 - 2022	All	All	3.0L LM2	All

Involved Region or Country	Canada and Mexico Vehicles Only
Additional Options (RPO)	With RPO UHS and LM2
Condition	Some customers may comment that they are unable to reset the fuel filter monitor system. When scrolling through the DIC there is no selection for fuel filter life.
Cause	Calibration

### Correction:

Currently, Engineering is working on a correction and when one becomes available this PI will be updated. In the meantime, for fuel filter maintenance please follow the "Maintenance Schedule" located in the "3.0L Duramax Diesel Engine Supplement" owner's manual.

### Version History

Version	2
Modified	05/11/2022 - Created on. 09/26/2022 - Updated to make a correction in the Correction Sections



GENERAL MOTORS