



Bulletin No.: PIC6476
Published date: 09/29/2022


Preliminary Information

PIC6476 Appearance of Surface Cracks on Rotors

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT5	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	J57 - Carbon Ceramic Rotors
Condition	A customer may comment that the carbon ceramic rotors on their vehicle appear to have cracks on the surface of the rotors.
Cause	This is a normal appearance and does not impact the performance or durability of the brake system.



Correction:

None - The cracks are cosmetic only and no repair or replacement is required.

Warranty Information

Version History

Version	1
Modified	09/29/2022 - Created on.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.