

2022MY Expedition
(ABS)
22-PU1010-MIL-LT

New Updates to Report.

A few modifications were made to help improve the illuminated malfunction indicator lamps. There is nothing you need to do.

Ford Power-Up software updates like this help us make improvements without the inconvenience of asking you to leave home. At Ford we value your satisfaction, and we respect your time.

2022MY Navigator
(ABS)
22-PU1010-MIL-LT

New Updates to Report.

A few modifications were made to help improve the illuminated malfunction indicator lamps. There is nothing you need to do.

Lincoln Enhance software updates like this help us make improvements without the inconvenience of asking you to leave home. At Lincoln we value your satisfaction, and we respect your time.