

ATTENTION:

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2022 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2022MY BRZ


NUMBER: 09-93-22

SUBJECT: Fuel Pipe / Torque Specification Change

DATE: 01/10/23

INTRODUCTION:

This Service Information Bulletin announces torque specification change for the fuel delivery pipe mounting bolt. The specification has been increased from 6.4 Nm to 9.0 Nm. Please torque to the new specification whenever mounting bolt removal is required. This change will be added to the Service manual in the future.



SERVICE PROCEDURE / INFORMATION:

When tightening the fuel delivery pipe mounting bolt, confirm the bolt is torqued to 9.0 Nm (6.6 ft-lb).

OLD Torque Specification	NEW Torque Specification
6.4 Nm (4.7 ft-lb)	9.0 Nm (6.6 ft-lb)

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.