

ATTENTION:

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2011MY and Later Legacy and Outback

NUMBER: 12-135-12R

SUBJECT: Sunroof Binding, Wedge Cap Adjustment Procedure Revisited

DATE: 07/30/12

REVISED: 03/14/13

NOTE: Service Bulletin 12-135-12R (Sunroof Binding, Wedge Cap Adjustment Procedure Revisited) has been deleted from STIS and has been replaced with Service Bulletin 07-72-13 (Sunroof Does Not Open or Close Properly, Popping or Slamming Sound When Glass Lowers Prior To Opening).

If you have copies of 12-135-12R please discard and refer to 07-72-13 for the latest repair procedure.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT"

The international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.