



# SERVICE BULLETIN

Classification: EL06-009	Reference: NTB07-002	Date: January 9, 2007
-----------------------------	-------------------------	--------------------------

## 2004 - 2007 TITAN/ARMADA; WASHER FLUID LEAKING FROM WASHER TANK PUMP SEAL

**APPLIED VEHICLES:** 2004 - 2007 Titan (A60)  
2004 - 2007 Armada (TA60)

### IF YOU CONFIRM

Washer fluid leaking at the washer pump seal on the washer tank.

### ACTION

Replace washer pump seal with the new one listed in Parts Information.

### PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Washer Pump Seal	16453 ZC30A	1

### CLAIMS INFORMATION

Submit a Primary Part (PP) type line using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL Washer Pump Seal	(1)	RG18AA	ZE	32	(2)

(1) Reference the A60/TA60 Parts Catalog and use the indicated Washer Tank Pump P/N as the PFP.

(2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.

**IMPORTANT:** The purpose of "ACTION" (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire Service Procedure (starting on page 2) as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## SERVICE PROCEDURE

1. Remove Washer Tank Assembly.
  - Refer to “Removal and Installation of Washer Tank” in the “WW” chapter of the ESM.



Figure 1

2. Remove washer motor and washer pump seal.
  - Photo of washer motor and washer pump seal.



Figure 2

3. Replace washer pump seal.

**NOTE:** Lubricate the pump seal with washer fluid to ease installation.

4. Install washer motor onto the washer tank.
5. Reinstall the washer tank in reverse order of removal.