

WORK DESCRIPTION FOR FIELD MEASURE

Code: 20P6890004

Version: 2.0

Replace side right cover at instrument panel

Model 118

Work procedure

1. Replace right cover (A, figure 1) at instrument panel.



Figure 1

Parts

Quantity	Designation	Part no.
1	Instrument panel cover (right)	*

* The replacement part for the vehicle identification number must be determined via the parts process in the XENTRY Portal!

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-1735	Replace side right cover at instrument panel	0.1 h	68 900 04

Mercedes-Benz
Global Service & Parts