

WORK DESCRIPTION FOR FIELD MEASURE

Code: 21P5493005

Version: 2.0

Replace steering column switch module

Model 223

i • Code 443 corresponds to STEERING WHEEL HEATER.

Work procedure

1. Replace steering column switch module.

i For basic data, see AR54.25-P-2812S.

Parts

Quantity	Designation	Part no.
As required (1)*	CONTROL UNIT COMPLETE, steering column switch module with code 443	A 223 900 95 28 8T92
As required (1)*	CONTROL UNIT COMPLETE, steering column switch module with code 443	A 223 900 95 28 9051

* The replacement parts must be determined according to the equipment variant for the vehicle identification number!

i Small parts such as screws/bolts, lock nuts, sealing rings, cable ties, fluids, sealants, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-0830	Replace steering column switch module Comprises: Disconnect/connect ground line of 12 V on-board electrical system battery; perform commissioning	1.0 h	54 930 05
02-4762*	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1 h	54 930 05
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	54 930 05

* Operation item may be invoiced only once for each workshop order!

Mercedes-Benz
Global Service & Parts