



GROUP
Climate Control

MODEL
2014MY
Soul (PS)

NUMBER
PS300

DATE
May 2014



TECHNICAL OPERATIONS

SUBJECT: INCORRECTLY ROUTED HIGH PRESSURE A/C LINE

Some 2014 Soul (PS) produced prior to February 7, 2014, may exhibit a concern related to poor performance from the A/C system, accompanied by low refrigerant. In such cases, check the routing for the A/C high pressure line to make sure it is not coming into contact with the accessory drive belt (see image). If the line has come into contact with the belt and has sustained damage, replace the line and recharge the system to resolve the concern.

