

Some 2014MY Forte vehicles, manufactured prior to September 2013, may exhibit a clicking type noise from the front suspension when carrying a full load of passengers and turning the wheel in either direction at low speeds; such as in a parking lot situation or when pulling into steeply inclined driveway. To correct this condition, place the vehicle on the lift, raise the dust cover and apply a generous amount of silicone based lubricant onto the left and right strut caps, as shown below.

