



# Service Bulletin

File in Section: -

Bulletin No.: PIP5279

Date: April, 2015

## PRELIMINARY INFORMATION

**Subject:** SES Lamp With Fuel Rail Pressure Codes

**Models:** 2015 Cadillac Escalade  
 2014-2015 Chevrolet Corvette  
 2014-2015 Chevrolet Silverado 1500 Suburban, Tahoe  
 2014-2015 GMC Sierra 1500 Yukon Yukon XL  
 Built with RPO's 4.3L 5.3L 6.2L L83 L86 LT1 LT4 LV3

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A vehicle may have a customer concern of an SES lamp with fuel rail pressure sensor codes

On investigation there may be any of the following codes P0089, p127C, P127D, P0192, P0193. P228C, P228D and P006C

### Recommendation/Instructions

Follow published Si diagnostics for the DTC's that have set, if it is inconclusive replace the FRPS (fuel rail pressure sensor).

Operate the vehicle under the condition for setting the DTC's if possible to determine if the codes reset.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4022490	Fuel Injection Fuel Rail Fuel Pressure Sensor Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.