



# Service Bulletin

File in Section: -

Bulletin No.: PIT5224

Date: August, 2013

## PRELIMINARY INFORMATION

**Subject:** Updated Left and Right I/P Fuse Block Labeling

**Models:** 2014 Chevrolet Silverado 1500  
2014 GMC Sierra 1500  
Built Prior to July 26, 2013 in Silao (11th Vin Position = G)


The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern


After inspecting the Left and/or Right I/P Fuse Block Labels, it may be noted the numbering is incorrect.

### Recommendation/Instructions

Inspect the lower right corner of each label for P/N 23114670 (Left) and/or P/N 23114671 (Right). If these part numbers are found, replace the label(s) with updated label(s): P/N 23207928 (Left) and P/N 23207929 (Right). See photos below of the updated labels.



3600974



3600975

## Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
1030630	Instrument Panel Fuse Block Access Hole Cover Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.