



Service Bulletin

File in Section: -

Bulletin No.: PIP5159

Date: October, 2013

PRELIMINARY INFORMATION

Subject: Engine Misfire May Be Due To Loose Spark Plug Wires

Models: 2014 Chevrolet Corvette
2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500
Built with engines 4.3L 5.3L 6.2L RPOs L83 L86 LT1 LV3

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

SES lamp on, DTC P0300 - P0308 may set. Upon inspection, a loose sparkplug wire may be found.

Recommendation/Instructions

If a loose sparkplug wire is found, reconnect it.

If the sparkplug wire does not snap on, the sparkplug wire will need to be replaced.

Warranty Information

For vehicles repaired under warranty use:

| Labor Operation | Description | Labor Time |
|-----------------|-----------------------------|------------------------------------|
| 4020050 | Spark Plug Wire Replacement | Use Published Labor Operation Time |

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.