



Service Bulletin

File in Section: -

Bulletin No.: PIC5965A

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Various Heating and Cooling Concerns With HVAC Control Module

Models: 2014 - 2015 Chevrolet Camaro

This PI was superseded to update Recommendation/Instructions. Please discard PIC5965.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment that any of the following conditions may be present at start-up:

- Blower motor and/or indicators are inoperative
- Blower motor may be blowing but speed cannot be adjusted

Upon further inspection, DTC U1510 may be set in the ECC (Electronic Climate Control) module. This module is commonly referred to as the HVAC module.

Recommendation/Instructions

If any of the concerns listed above are encountered, technicians are to reprogram the ECC module. An updated ECC module software calibration has been released to address these concerns.

Refer to the HVAC System Control Module Programming and Setup procedures in SI.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810015	HVAC System Control Module Reprogramming with SPS	Use Published Labor Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.