



# Service Bulletin

File in Section: -

Bulletin No.: 15-NA-058

Date: November, 2015

## TECHNICAL

**Subject: Squeak, Squawk, Creak or Popping Noise Originating from Rear Axle**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Volt	2016	2016			All	All

<b>Condition</b>	Some customers may comment on a squeak, squawk, creak or popping noise in the rear of the vehicle when driving or traveling over bumps in the road.
------------------	---

### Correction

If the noise is verified to be originating from the rear axle, do **NOT** replace any parts for this issue.

Engineering is aware of this condition and working on a resolution. Once a solution becomes available, this Bulletin will be updated.

### Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this Bulletin will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION